

Certificate of Compliance

Class One Cleanroom Systems

29722 AVENIDA DE LAS BANDERAS, RANCHO SANTA MARGARITA, CA
949.589.9008

One 200 sq. ft. Cleanroom

Positive pressure Cleanroom ISO 7 Class 10,000

Illuminant CBD

32401 Calle Perfecto San Juan Capistrano

Meets or Exceeds requirements of ISO 7 14644

Class 10,000

Airborne Particle

At 0.5 MICRON in OPERATION MODE

Test Date 12/11/2019

Retest date 12/11/2020

PAUL VARNI

Paul Varni

PRESIDENT